



Republic of the Philippines
SURIGAO DEL NORTE STATE UNIVERSITY
Narciso Street, Surigao City 8400, Philippines



OFFICE OF THE BIDS & AWARDS COMMITTEE

SUPPLEMENTAL/BID BULLETIN NO. 1

Reference No.: PB# 25-04-0009

Title: Repair of College Building - Malimono Campus

Subject: Addendum

1. Certificate of site inspection duly signed by the Campus Director and Head of the Buildings & Estates. The site inspection schedule will be on **May 7, 2025, @ 9:00 PM - 12:00 NN**.
2. A final rating of at least **Satisfactory** in the *Constructors Performance Evaluation System (CPES)* is required for **SLCC**.
3. SPA and a copy of PCAB are required for those representatives of the company to purchase bidding documents and participate in the site inspection.
4. A Clearance Certificate issued by the Department of Labor and Employment. (No Pending Labor Case)

For your guidance and information.

MR. JONAS ROBERT L. MIRANDA
BAC Chairperson

Received by the Bidder: _____